




Inlet air at 1013 mbar pressure & 15° C
temperture belt pull must not exceed
2450 N maximum pressure 1035 mbar

B:
Pressure
Rise mbar

200
400
600
800
1000

140
120
100
80
60
40
20
0
deg C
E: Temp. Rise

1035
1000
800
600
400
200
0
kw
D: Absorbed Power



SR015